


REFERENCE DEFECT

Reference defects to check for cracks and pores



Accurate setting and checking. For the exact setting and the cyclic inspection of eddy current test equipment, setting masters of the test parts with reference defects are required. Natural defects cannot be used for this purpose, as they are not reproducible and often do not exist.

FOERSTER can use the die-sinking EDM process to introduce reference flaws into your workpiece for testing of cracks and pores.

National and international standards or corresponding customer specifications apply as defaults. The setting defects are measured and subsequently receive a certificate according to DIN EN ISO 9001.

For better documentation, the setting masters can be engraved or clearly marked with laser.

TECHNICAL INFORMATION

DEFECTS	
WIDTH:	0.04 mm – 1.0 mm
DEPTH:	0.02 mm – 5.0 mm
LENGTH:	0.50 mm – 40.00 mm (other dimensions on request)
PORES	
SIZE:	Ø 0.2 mm – 3 mm
DEPTH:	0.02 – 5 times diameter (further dimensions on request)
BOREHOLE	from a diameter of 0.2 mm - depending on material thickness and properties



foerstergroup.com



The FOERSTER Group is represented by subsidiaries and representatives in over 60 countries worldwide. You can find a complete overview on our website.

Headquarters

Institut Dr. Foerster GmbH & Co. KG

In Laisen 70
72766 Reutlingen
Germany

+49 7121 140 0
info@foerstergroup.com

© Copyright 2026 – Copyright notice: All contents of this work, in particular texts, photographs and graphics, are protected by copyright. Unless explicitly stated otherwise, the copyright lies with Institut Dr. Foerster GmbH & Co. KG. Please contact us if you wish to use any part of this work.

Generated: 2026-09-22 07:48:23